

Date: Wednesday, 1/31/2007 2:19:10 PM
 User: Kim Johnston

Process Sheet

Customer : CU-DAR001 Dart Helicopters Services	Drawing Name : BUSHING
Job Number : 30557	
Estimate Number : 10503	
P.O. Number : <u>N/A</u>	Part Number : D2745
This Issue : 1/31/2007 S.O. No. : <u>N/A</u>	Drawing Number : D2745 REV B
Prsht Rev. : NC	Project Number : N/A
First Issue : <u>N/A</u> Type : MACHINED PARTS	Drawing Revision : B
Previous Run : 29437	Material : <u>N/A</u>
Written By : _____	Due Date : 2/20/2007
Checked & Approved By : <u>07.02.01</u>	Qty: <u>100</u> Um: <u>Each</u>
Comment : Est C 02.03.07 Update to turn in house NG	

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	M303R0750	303 Round Bar .75"
-----	-----------	--------------------



Comment: Qty.: 0 f(s)/Unit Total : 0 f(s) 18'
 303 ROUND .75"
 Machine per Folio FA201 Material: AISI 303 SS

Batch: 104397SG 07.05.18

2.0	HARDINGE	HARDINGE CNC LATHE SMALL
-----	----------	--------------------------



Comment: HARDINGE CNC LATHE SMALL
 1-Turn as per Dwg D2515
 2-Deburr

SG 07.05.17100

3.0	QC2	INSPECT PARTS AS THEY COME OFF MACHINE
-----	-----	--



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

SG 07.05.17100

4.0	QC8	SECOND CHECK
-----	-----	--------------



Comment: SECOND CHECK

SL 07/05/18

5.0	SMALL FAB 1	SMALL & MEDIUM FAB RESOURCE 1
-----	-------------	-------------------------------



Comment: SMALL & MEDIUM FAB RESOURCE 1
 Tumble & deburr any sharp edges as per dwg

SA 07.06.04

6.0	QC5	INSPECT WORK TO CURRENT STEP
-----	-----	------------------------------



Comment: INSPECT WORK TO CURRENT STEP

SB 07/06/18(100)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes ☒ No ☐ DQA: ☒ _____ Date: 07/06/19
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 1/31/2007 2:19:10 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BUSHING

Job Number: 30557

Part Number: D2745

Job Number:



Seq. #:

Machine Or Operation:

Description :

7.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and stock

Location: *FF-7*

FX 07/06/18 ~~100~~ *(100)*

8.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

07/06/19

Job Completion



U 07/06/18

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____


NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN <i>DA</i>	DRAWN BY <i>CP</i>	DART AEROSPACE USA, INC. FAIRCHILD INTERNATIONAL AIRPORT, WA	
CHECKED <i>DA</i>	APPROVED <i>KE</i>	DRAWING NO. D2745	REV. B SHEET 1 OF 1
DATE 98.10.23		TITLE BUSHING	SCALE 2:1
A	98.04.16	NEW ISSUE	
B	98.10.23	DIM 0.400 WAS 0.380	

RELEASED
98.11.03 DS



MATERIAL: AISI 303 STAINLESS STEEL

NOTES: TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

RADIUS ALL INSIDE EDGES 0.005 TO 0.010

BREAK ALL UNMARKED SHARP EDGES 0.010 TO 0.020

ALL DIMENSIONS ARE IN INCHES

SHOP COPY
RETURNED
ENGINEERING
CONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 30557